

序号	报告编号	发布日期	结论	影像资料
7	GX-B1559/22-Y-25011	2025. 9. 9	所检项目合格。	
8	GX-B1539/22-Y-25052	2025. 9. 9	所检项目合格。	

9	GX-B1539/22-Y-25053	2025. 9. 9	所检项目合格。	
10	GX-B1350/21-Y-25003	2025年9月10日	本次共检接地装置 2处，2处接地装置所 检项目合格	

11	GX-B1310/21-Y-25124	2025. 9. 5	符合标准要求。	 <p>2025.8.4</p>
12	GX-B1310/21-Y-25125	2025. 9. 5	符合标准要求。	 <p>2025.8.10</p>

13	GX-B1515/22-Y-25012	2025. 9. 15	所检项目合格。	 A black and white photograph of a worker wearing a hard hat and safety glasses, focused on a task. The worker is positioned in front of what appears to be a control panel or a set of electrical equipment. The lighting is somewhat dim, highlighting the worker's concentration. A small red date stamp '2025.9.15' is visible in the bottom right corner of the image.
14	GX-B1495/20-Y-25535~25536	2025. 9. 15	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	 A color photograph showing a worker in a white safety jacket and a prominent red hard hat. The worker is standing in an industrial setting, likely a substation, and is engaged in inspecting or working on a large, complex piece of electrical equipment, identified as a high-voltage switchgear cabinet. The equipment has various panels, dials, and cables. A red date stamp '2025.9.15' is located in the bottom right corner of the image.