

序号	报告编号	发布日期	结论	影像资料
152	GX-B1364/22-A-25996	2025/10/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
153	GX-B1364/22-A-25997	2025/10/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
154	GX-B1364/22-A-25998	2025/10/20	所检项目合格。	 A photograph showing two men in white uniforms working on a large industrial machine. One man is standing closer to the machine, while the other is further back. The machine has a control panel with a screen and various buttons. The date "2025.10.16" is visible in the bottom right corner of the image. 2025.10.16

序号	报告编号	发布日期	结论	影像资料
155	GX-B1364/22-A-25999	2025/10/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
156	GX-B1364/22-A-25994	2025/10/20	所检项目合格。	 A photograph showing two men in an industrial environment. One man, wearing a light-colored jacket, is facing away from the camera, looking at a control panel with a screen and several buttons. Another man, also in a light-colored jacket, is standing next to him, facing the first man. The background shows industrial equipment and pipes. A timestamp "2025.10.15" is overlaid in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
157	GX-B1364/22-A-251001	2025/10/20	所检项目合格。	 2025.10.16

序号	报告编号	发布日期	结论	影像资料
158	GX-B1364/22-A-251002	2025/10/20	所检项目合格。	 2025.10.16

序号	报告编号	发布日期	结论	影像资料
159	GX-B1364/22-A-251000	2025/10/20	所检项目合格。	 2025.10.16

序号	报告编号	发布日期	结论	影像资料
160	GX-B1363/25-A-25523	2025/10/21	所检项目合格。	 A photograph showing two men in light-colored shirts with blue "中公信" (ZGXX) logos on the sleeve. They are inspecting the interior of a large, dark, metallic industrial oven or kiln. The oven has a prominent chimney pipe at the top. The date "2025.10.13" is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
161	GX-B1363/25-A-25522	2025/10/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
162	GX-B1365/25-A-25092	2025/10/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
163	GX-B1366/25-A-25116	2025/10/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
164	GX-B1363/25-A-25532	2025/10/21	所检项目合格。	 <p>2025.10.20</p>

序号	报告编号	发布日期	结论	影像资料
165	GX-B1366/25-A-25117	2025/10/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
166	GX-B1366/25-A-25114	2025/10/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
167	GX-B1366/25-A-25115	2025/10/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
168	GX-B1367/22-A-25071	2025/10/22	所检项目合格。	 2025.10.20

序号	报告编号	发布日期	结论	影像资料
169	GX-B1363/25-A-25529	2025/10/22	所检项目合格。	 2025.10.17

序号	报告编号	发布日期	结论	影像资料
170	GX-B1363/25-A-25530	2025/10/22	所检项目合格。	 2025.10.17

序号	报告编号	发布日期	结论	影像资料
171	GX-B1367/22-A-25070	2025/10/23	所检项目合格。	 2025.10.20

序号	报告编号	发布日期	结论	影像资料
172	GX-B1367/22-A-25069	2025/10/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
173	GX-B1363/25-A-25531	2025/10/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
174	GX-B1458/22-A-25023	2025/10/24	所检项目合格。	 2025.10.22

序号	报告编号	发布日期	结论	影像资料
175	GX-B1458/22-A-25024	2025/10/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
176	GX-B1364/22-A-251003	2025/10/22	所检项目合格。	 A photograph showing two men from behind, working on a large industrial machine. The man on the left wears a white shirt with '中检公信' (China Inspection & Certification) printed on the back. The man on the right wears a grey shirt. They are both looking at a control panel with a screen and several buttons. The date '2025.10.20' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
177	GX-B1509/20-A-25046	2025/10/24	所检项目合格。	 2025.10.22

序号	报告编号	发布日期	结论	影像资料
178	GX-B1365/25-A-25093	2025/10/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
179	GX-B1366/25-A-25118	2025/10/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
180	GX-B1363/25-A-25541	2025/10/24	所检项目合格。	 2024.12.31

序号	报告编号	发布日期	结论	影像资料
181	GX-B1363/25-A-25521	2025/10/27	所检项目合格。	 A photograph showing two men in light-colored work uniforms inspecting a large industrial furnace or kiln. One man is standing on the left, facing away from the camera, while the other is on the right, looking into the open furnace. The furnace has a prominent cylindrical chimney at the top. The date "2025 10.11" is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
182	GX-B1363/25-A-25536	2025/10/27	所检项目合格。	 A photograph showing two men in a workshop setting. One man, wearing a light-colored shirt, is standing on the left, looking into the open door of a large, industrial-grade oven or kiln. The other man, wearing a grey jacket with a logo on the sleeve and red gloves, is standing on the right, holding the open door of the oven. The oven has a prominent chimney pipe above it. The date "2025.10.21" is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
183	GX-B1363/25-A-25539	2025/10/27	所检项目合格。	 2025.10.22

序号	报告编号	发布日期	结论	影像资料
184	GX-B1363/25-A-25537	2025/10/27	所检项目合格。	 2025.10.22

序号	报告编号	发布日期	结论	影像资料
185	GX-B1363/25-A-25540	2025/10/29	所检项目合格。	 2025.10.23

序号	报告编号	发布日期	结论	影像资料
186	GX-B1363/25-A-25542	2025/10/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
187	GX-B1363/25-A-25543	2025/10/29	所检项目合格。	 A photograph showing two men in light-colored work uniforms inspecting an industrial furnace. The man on the left is wearing a blue apron and has his back to the camera. The man on the right is wearing a white shirt with a 'CIG 中检公信' logo on the sleeve and is facing the furnace. The furnace is large and made of metal, with a door open. A pipe is visible above the furnace. The date '2025.10.24' is overlaid in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
188	GX-B1364/22-A-251004	2025/10/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
189	GX-B1364/22-A-251005	2025/10/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
190	GX-B1364/22-A-251006	2025/10/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
191	GX-B1364/22-A-251007	2025/10/29	所检项目合格。	 A photograph showing two men in industrial-style clothing working in a control room. One man is facing away from the camera, looking at a large black control panel with multiple digital displays and buttons. The other man is partially visible behind him, also focused on the equipment. The control panel has a digital screen at the top and several analog-style gauges or meters below it. The date "2025 10.23" is printed on the panel. In the background, there's a blue cabinet and some pipes.

序号	报告编号	发布日期	结论	影像资料
192	GX-B1364/22-A-251008	2025/10/29	所检项目合格。	 2025.10.23

序号	报告编号	发布日期	结论	影像资料
193	GX-B1364/22-A-251009	2025/10/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
194	GX-B1364/22-A-251010	2025/10/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
195	GX-B1364/22-A-251011	2025/10/29	所检项目合格。	 2025 10.24

序号	报告编号	发布日期	结论	影像资料
196	GX-B1364/22-A-251012	2025/10/29	所检项目合格。	 2025.10.24

序号	报告编号	发布日期	结论	影像资料
197	GX-B1364/22-A-251013	2025/10/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
198	GX-B1364/22-A-251014	2025/10/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
199	GX-B1364/22-A-251015	2025/10/29	所检项目合格。	 2025.10.24

序号	报告编号	发布日期	结论	影像资料
200	GX-B1364/22-A-251016	2025/10/29	所检项目合格。	 A photograph showing two technicians in grey uniforms with blue "中公信" (ZGXX) logos on the back. They are standing in front of a large industrial machine with a control panel featuring a touchscreen display and several physical buttons. The technician on the right is wearing a face mask and glasses, and is pointing at the screen. The technician on the left is facing away from the camera. The background shows a workshop environment with a window and some equipment. A timestamp "2025.10.24" is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
201	GX-B1364/22-A-251017	2025/10/29	所检项目合格。	 A photograph showing two men in light-colored work uniforms and safety glasses. One man is wearing a white respirator mask and yellow gloves, standing next to a large industrial control panel with a digital display and several knobs. The other man is seen from behind, also near the machine. The control panel has a date stamp "2025.10.24".

序号	报告编号	发布日期	结论	影像资料
202	GX-B1364/22-A-251018	2025/10/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
203	GX-B1364/22-A-251019	2025/10/29	所检项目合格。	 A photograph showing two men in light-colored work uniforms and safety gear, including a respirator mask and gloves, standing next to a large industrial control panel. The panel has a digital screen and several analog dials. The man on the right's uniform features a logo and the text '中检公信' (China Inspection & Certification). A timestamp '2025.10.24' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
204	GX-B1364/22-A-251020	2025/10/29	所检项目合格。	 A photograph showing two men in light-colored work uniforms and safety gear (including a respirator mask) standing next to a large industrial control panel. The panel features a touchscreen display and several analog dials. One worker is facing the camera, while the other is seen from behind. The date '2025.10.24' is visible on the right side of the panel.

序号	报告编号	发布日期	结论	影像资料
205	GX-B1363/25-A-25545	2025/10/30	所检项目合格。	 A photograph showing two men in light-colored work uniforms inspecting a large industrial oven or kiln. The oven has a prominent chimney pipe. One man is facing the oven while the other stands beside him. The date "2025.10.25" is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
206	GX-B1363/25-A-25544	2025/10/30	所检项目合格。	 2025.10.24

序号	报告编号	发布日期	结论	影像资料
207	GX-B1364/22-A-251021	2025/10/31	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
208	GX-B1364/22-A-251022	2025/10/31	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
209	GX-B1364/22-A-251023	2025/10/31	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
210	GX-B1364/22-A-251024	2025/10/31	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
211	GX-B1364/22-A-251025	2025/10/31	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
212	GX-B1364/22-A-251026	2025/10/31	所检项目合格。	 A photograph showing two men in industrial settings. One man is seen from behind, wearing a light-colored shirt. The other man is facing him, wearing a grey jacket over a green shirt. They appear to be inspecting or operating a piece of machinery. To the right, there is a control panel with a screen and several knobs, displaying the date "2025.10.27".

序号	报告编号	发布日期	结论	影像资料
213	GX-B1364/22-A-251027	2025/10/31	所检项目合格。	 A photograph showing two men in work uniforms inspecting a piece of industrial machinery. One man is facing the machine, which has a control panel with a screen and several gauges. The other man is standing behind him, looking at the same panel. The machine has some text and logos on it, including 'ELUX' and '2222A'. In the bottom right corner of the photo, there is a timestamp '2025.10.27'. The man in the foreground's uniform has blue text that appears to read '中检公信'.

序号	报告编号	发布日期	结论	影像资料
214	GX-B1366/25-A-25112	2025/10/31	所检项目全部合格。	